





49 Bay Road
Seawall


Aerial view of property showing neighboring wall conditions




Existing, eroding wall looking westerly



Existing, eroding wall looking easterly



Design precedent



Wall showing dry laid boulders. Boulders in water help diffuse wave action and erosion but limit water use