


NOTE:

- INSPECT AND REPAIR FENCE AFTER EACH STORM EVENT AND REMOVE SEDIMENT WHEN NECESSARY.
- REMOVED SEDIMENT SHALL BE DEPOSITED TO AN AREA THAT WILL NOT CONTRIBUTE SEDIMENT OFF-SITE AND CAN BE PERMANENTLY STABILIZED.
- SILT FENCE SHALL BE PLACED ON SLOPE CONTOURS TO MAXIMIZE PONDING EFFICIENCY.


**SILT FENCE**

Map Reference:  
Boundary Survey Prepared for  
Stuart Flood, Darley Road & Flat  
Brook Road, East Hampton, Conn.  
Scale 1"=100', June 3, 1983, by  
Frederick M. Hayes Associates, Inc., P.C.



**LEGEND**

○ I.P. Fnd.	IRON PIPE FOUND
● I.P. T.S.	IRON PIN TO BE SET
■ MON. Fnd.	MONUMENT FOUND
■ MON. SET	MONUMENT SET
N/F	NOW OR FORMERLY
R	RADIUS
L	LENGTH
Δ	DELTA ANGLE
No.	NUMBER
N.T.S.	NOT TO SCALE
RY	REAR YARD
SY	SIDE YARD
BL	BUILDING LINE



MAP CERTIFICATE:  
THIS SURVEY AND MAP HAS BEEN PREPARED IN ACCORDANCE WITH SECTIONS 20-300b-1 THRU 20-300b-20 OF THE REGULATIONS OF THE CONNECTICUT STATE AGENCIES-MINIMUM STANDARDS FOR SURVEYS AND MAPS IN THE STATE OF CONNECTICUT AS ENFORCED BY THE CONNECTICUT STATE ASSOCIATION OF LAND SURVEYORS, INC. THIS MAP CONFORMS TO A HORIZONTAL ACCURACY CLASS OF 4-2 THE SURVEY TYPE IS RESURVEY BASED ON EXISTING MAPS AND FIELD EVIDENCE.  
AND IS INTENDED TO BE USED IMPROVEMENT SURVEY

TO MY KNOWLEDGE AND BELIEF, THIS MAP IS SUBSTANTIALLY CORRECT AS NOTED HEREIN.

REVISIONS:	PLOT PLAN FOR <b>ALDO ZPICH &amp; CHERYL VANGHAN</b> LOT 3, BLOCK 92 & MAP 34 164 DALY ROAD EAST HAMPTON CONNECTICUT				
	<b>J L SURVEYING</b> 212 OLD BRICKYARD LANE Berlin Connecticut Phone 860-828-3200				
DATE	Plot Date: 8-10-19	FILE NAME	C:\DRAW\2018\21916\164 DALY RD	PROJECT NO.	21916
DRAWN BY	JL	SHEET NO.	1 OF 1		