

RECEIVED
10.27.2021
East Hampton
Land Use Office



Photo of the original house and seawall, circa 1990

Original home had a poured cement patio and cement/stone seawall with no vegetation border in front of the seawall



Photo of current house and eroding land. See photos below to see exposed tree roots. We are concerned about losing the large, mature trees to erosion

New patio includes a wide vegetation border for clover and native plants to prevent run-off




Existing edge of old seawall, note tree roots exposed due to erosion



Proximity of mature trees to eroded edge. Wide strip of vegetation to be planted with clover and native plants

RECEIVED
10.27.2021
East Hampton
Land Use Office

Existing View showing collapsed wall and existing plantings



31 Bay Road
Sea Wall restoration
plan

Plant low shrubs and
plantings between wall
and patio area

Approx 7 feet

Secure with limited
mortar as needed

Rebuild / Reset
existing stones with
other stones from the
old wall

Add ¾" stone backing
with filter fabric

