



PHOTO: 01
LOCATION: Northern Section
DESCRIPTION: Assorted paint and solvent storage area.



PHOTO: 02
LOCATION: Northern Section
DESCRIPTION: In-ground hydraulic lift



PHOTO: 03
LOCATION: Northern section
DESCRIPTION: Vehicle storage



PHOTO: 04
LOCATION: Central Section
DESCRIPTION: Exposed subfloor



PHOTO: 05
LOCATION: Central Section
DESCRIPTION: Pump House



PHOTO: 06
LOCATION: Outside southern perimeter of property
DESCRIPTION: Empty 300-gallon above ground storage tanks



PHOTO: 07

LOCATION: Western extent of exterior property

DESCRIPTION: Photograph taken February 2004. Photograph illustrates soil staining.



PHOTO: 08

LOCATION: Western extent of property.

DESCRIPTION: Outside building facing Watrous Street.